| <b>ECS</b> Configuration   | on Change Request   |   |   | P   | age 1 of                                       | Pa   | age(s)   |  |
|--|---|---|---|---|--|--|--|--|
| 1. Originator  | 2. Log Date:  | 3. CCR #:   | 4. F  |   |  | 6. Rm #:   | - Annual Control of the Control of t |  |
| Sarah Lewallen   | 11/30/00  | 00-11   | ماا   | 301-  | 925-0865                                       | 2117b  | SED  |  |
| 8. CCR Title: Hardware   | installions for SPR and FSM   | IS at LaRC; CPI   | J ugrade at G                                 | SFC; Giga                                   | bit card move                                  | e to EDC.  |  |  |
| 9. Originator Signature/Date Sarah Lewallen  |   |   | 10. Class                                     | s 11. Type:<br>CCR                          |  | 12. Need Date: 12/15/00                                  |  |  |
| 13. Office Manager Signature/Date  Randy Hayner  |   |   | 14. Catego<br>Update EC                       |   | Doc. fil                                       | 15. Priority: (If "Emergency" fill in Block 28), Routine |  |  |
| 16. Documentation/Drawings Impacted:<br>see attached   |   |   | NATE:   |   | S. CI(s) Affe<br>Dspg10,e0acg                  | ) Affected:10spg10, 10drg04,<br>e0acg11                  |  |  |
| 19. Release Affected N/A   |   | 20. Date due to Customer:<br>12/30/00   |   | 21. Estimated Cost:<br>None - Under 100K    |  |  |  |  |
| 22. Source Reference:<br>Procurement - CCR 00-   |   | ction Item  | Tech Ref.                                     | GSFC  | ⊠Other:  |  |  |  |
| An Origin 3000 will be a<br>the existing SPR RAID.<br>during conversion, and<br>configured with 8CPUs<br>GSFC for g0spg10. The<br>25. Alternate Solution | n: (use additional sheets if<br>trriving at LaRC. Install the now<br>The Origin 2000 will be move<br>will replace lodrg01 as the pre<br>and 4GB of RAM using IRIX<br>of Gigabit ethernet card will be<br>trace; (use additional sheets if<br>and ship the entire 2000 to Gi | new 32 CPU 300<br>yed to the FSMS<br>rimary FSMS set<br>6.5.6 and 100 b<br>moved to EDC<br>necessary) | subsystem a<br>rver after con<br>ase T. 8 CPU | s host "10di<br>version. It v<br>Js and the | rg04" This w<br>vill be added<br>the balance o | rill be used to<br>to the netwo<br>of memory wi          | o host Silo 1<br>irk and<br>ill be moved to  |  |
|  | Change(s) are not approved<br>ts from the F&PRS at GSFC   |   |   | necessary                                   | )  |  |  |  |
| 27. Justification for E  | mergency (If Block 15 is "E   | Emergency"):  |   |   |  |  |  |  |
| 28. Site(s) Affected:  |   |   | gsfc ⊠L                                       | aRC 🗆                                       | ISIDC S  | MC DAK   | □JPL   |  |
| 29. Board Comments:  | EOC DIDG Test Cell  | Other   | 3   | 0. Work A                                   | ssigned To:                                    | 31. CCR  | Closed Date:   |  |
| 32. EDF/SCDV CCB C   | hair (Sign/Date):   | Disposition: A  | pproved App                                   | o/Com. Di                                   | sapproved 1                                    | Withdraw Fr  | wd/ESDIS ERB   |  |
| 33. M&O CCB Chair (S   | Sign/Date):   | Disposition: A  | -   | /Com. Di                                    | sapproved                                      | Withdraw Fu  | wd/ESDIS ERB   |  |
| 34. ECS CCB Chair (S   | iign/Date): D   |   | proved App                                    | /Com. Di                                    | sapproved                                      | Withdraw F   | wd/ESDIS ERB   |  |

ORIGINAL ECS/EDF/SCDV/M&O

## ADDITIONAL SHEET

CCR #: 00-1114 Rev: Originator: Sarah Lewallen

Telephone: 301-925-0865 Office: 2117b

Title of Change: Hardware installions for SPR and FSMS at LaRC; CPU ugrade at GSFC; Gigabit card move to EDC.

Documents impacted

923-TDL-007

921-TDL-003

923-TDL-002

923-TDL-005

921-TDL-002

920-TDE-001

920-TDG-001

920-TDL-001

922-TDL-007

920-TDL-002 - this document will not be updated until IRIX 6.5.6 moves into production All hardware and infrastructure maps already show these systems and power is in place

CM01AJA00

